

## FIFTH AMENDATORY AGREEMENT

**THIS FIFTH AMENDATORY AGREEMENT** is made between the **CITY AND COUNTY OF DENVER**, a municipal corporation of the State of Colorado (“City”) and **CENTURY HELICOPTERS, INC.**, a Colorado corporation, whose address is 2001 Airway Avenue, Fort Collins, Colorado 80524 (“Contractor”), collectively the “Parties”.

### WITNESSETH:

**WHEREAS**, the City and the Contractor entered into an agreement dated September 5, 2006, and amended the agreement on August 7, 2007, June 16, 2009, July 11, 2011 and August 7, 2013 for scheduled and non-scheduled maintenance of the Denver Police Department’s helicopter for the purpose of maintaining optimal air worthiness status (collectively the “Agreement”); and

**WHEREAS**, the Parties desire to amend the Agreement to extend the term and update the scope of work and rates.

**NOW, THEREFORE**, in consideration of the premises and the mutual covenants and obligations herein set forth, the Parties agree as follows:

**1.** Article 1 of the Agreement, **WORK TO BE PERFORMED**, is amended by the addition of the following paragraph at the end of the Article:

“In addition to the services previously described herein, for the period of time from July 1, 2015 through June 30, 2016, the Contractor agrees to provide the updated services at the rates and costs set out forth in **Exhibit A-5**, attached hereto and incorporated herein by this reference. The Contractor agrees to provide all services in a workman like manner, consistent with the manufacturer’s instructions and recommendations and the terms and conditions of the Agreement.”

**2.** Article 3 of the Agreement, entitled “**TERM OF AGREEMENT**”, is hereby amended to read as follows:

“**3. TERM OF AGREEMENT**: The term of the Agreement shall commence on June 1, 2006 and terminate on June 30, 2016 unless otherwise terminated earlier under the terms of this Agreement.”

**2.** Except as herein amended, the Agreement is affirmed and ratified in each and every particular.

[SIGNATURE PAGES FOLLOW]

Contract Control Number: POLIC-CE61220-05

Contractor Name: CENTURY HELICOPTERS INC

By: 

Name: Michael E. Hansen  
(please print)

Title: General Manager  
(please print)

**ATTEST: [if required]**

By: \_\_\_\_\_

Name: \_\_\_\_\_  
(please print)

Title: \_\_\_\_\_  
(please print)



**Contract Control Number:**

IN WITNESS WHEREOF, the parties have set their hands and affixed their seals at Denver, Colorado as of

SEAL

**CITY AND COUNTY OF DENVER**

ATTEST:

By \_\_\_\_\_

\_\_\_\_\_

APPROVED AS TO FORM:

REGISTERED AND COUNTERSIGNED:

By \_\_\_\_\_

By \_\_\_\_\_

By \_\_\_\_\_



EXHIBIT A-5

This contract amendment will cover any rate increases; scheduled and on-demand timeframe for unit inspections, maintenance, and major overhauls through the period of June 30, 2016.

Scheduled Professional Services	\$ 56,397.00
Rental Cost (Hours 13,653.8 – 14,278.7)	\$ 20,625.00
Shipping	\$ 2,500.00
On Board Equipment Cost	\$ 30,000.00
On Condition Equipment Cost	\$ 30,000.00
Contingency Cost 10%	<u>\$ 13,952.00</u>
<b>TOTAL PROJECTED EXPENSES (07/01/2015-06/30/2016)</b>	<b>\$153,474.00</b>

Aircraft Projection Report

Aircraft Registration  
 Aircraft Serial Number  
 Date Report Generated

N710DP  
 53249  
 2/6/2015

Century Helicopters, Inc.  
 2001 Airway Avenue  
 Fort Collins, CO 80524  
 USA

Phone: +1 (970) 484-6804  
 FAX: +1 (970) 224-3899  
 E-Mail: century@centuryhelicopters.com  
 Web Site: www.centuryhelicopters.com

Projection Start Hours  
 Projection Start Date  
 Projection End Hours  
 Projection End Date

13609.7  
 7/1/2015  
 14284.7  
 6/30/2016

Item	Description	Limit Type	Limit	Time Due	Date Due	Parts Cost	Labor Cost	Misc Cost	Admin Cost	Total
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	6	13625.3	42186	\$ -	\$ 21.25	\$ -	\$ -	\$ 21.25
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13662.6	42186	\$ 50.00	\$ 170.00	\$ -	\$ -	\$ 220.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13662.7	42186	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	150	13662.7	42186	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13662.7	42186	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13712.6	42217	\$ -	\$ 21.25	\$ -	\$ -	\$ 21.25
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13712.6	42217	\$ -	\$ 21.25	\$ -	\$ -	\$ 21.25
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13712.6	42217	\$ 50.00	\$ 170.00	\$ -	\$ -	\$ 220.00
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13712.6	42217	\$ -	\$ 255.00	\$ -	\$ -	\$ 280.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13712.6	42217	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
23077067	Fuel Nozzle	Overhaul	2000	13730.5	42217	\$ 1,528.88	\$ 170.00	\$ 25.00	\$ 25.50	\$ 1,749.38
Lubricate Pitch change Mechanism	IAW Chptr 12 Tbl 12-6	Inspection	3	13735.2	42248	\$ 10.00	\$ 42.50	\$ -	\$ -	\$ 52.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13762.6	42248	\$ 50.00	\$ 170.00	\$ -	\$ -	\$ 220.00
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	12	13790.1	42278	\$ 100.00	\$ 850.00	\$ -	\$ -	\$ 950.00
300 Hr/Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	12	13790.1	42278	\$ -	\$ 21.25	\$ -	\$ -	\$ 21.25
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	12	13790.1	42278	\$ -	\$ 21.25	\$ -	\$ -	\$ 21.25
300HR Search Light Insp	IAW S10899-01A	Inspection	6	13790.1	42278	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
ASB 407-14-106	Freewheel Oil Supply Blockage	Inspection	12	13790.1	42278	\$ 15.00	\$ 127.50	\$ -	\$ -	\$ 142.50
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	12	13790.1	42278	\$ 100.00	\$ 85.00	\$ -	\$ -	\$ 185.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	12	13790.1	42278	\$ 15.00	\$ 42.50	\$ -	\$ -	\$ 57.50
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	12	13790.1	42278	\$ 50.00	\$ 127.50	\$ -	\$ -	\$ 177.50
Inspect Filtestep Kit	AAI Filtestep Kit IAW AA-01162 Rev E	Inspection	12	13790.1	42278	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	12	13790.1	42278	\$ -	\$ 21.25	\$ -	\$ -	\$ 21.25
Periodic 300Hr Inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	12	13790.1	42278	\$ 200.00	\$ 3,570.00	\$ -	\$ -	\$ 3,770.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13812.6	42278	\$ -	\$ 21.25	\$ -	\$ -	\$ 21.25
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13812.6	42278	\$ -	\$ 21.25	\$ -	\$ -	\$ 21.25
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13812.6	42278	\$ 25.00	\$ 170.00	\$ -	\$ -	\$ 220.00
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13812.6	42278	\$ -	\$ 255.00	\$ -	\$ -	\$ 280.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13812.6	42278	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	13812.7	42278	\$ 100.00	\$ 850.00	\$ -	\$ -	\$ 950.00
300 Hr/Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	13812.7	42278	\$ -	\$ 21.25	\$ -	\$ -	\$ 21.25
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	13812.7	42278	\$ -	\$ 21.25	\$ -	\$ -	\$ 21.25
300HR Search Light Insp	IAW S10899-01A	Inspection	300	13812.7	42278	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
ASB 407-14-106	Freewheel Oil Supply Blockage	Inspection	300	13812.7	42278	\$ 15.00	\$ 127.50	\$ -	\$ -	\$ 142.50
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13812.7	42278	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	150	13812.7	42278	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	13812.7	42278	\$ 100.00	\$ 85.00	\$ -	\$ -	\$ 185.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	13812.7	42278	\$ 15.00	\$ 42.50	\$ -	\$ -	\$ 57.50
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	13812.7	42278	\$ 75.00	\$ 42.50	\$ -	\$ -	\$ 117.50

Clean or Change hydraulic Filters & Change Fluid	I/AW Chptr 12 Tbl 12-3	Inspection	300	13812.7	42278	\$ 50.00	\$ 127.50	\$ -	\$ -	\$ -	\$ 177.50
Inspect and Lube T/R/D/S Hangar Bearings	I/AW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	13812.7	42278	\$ 15.00	\$ 42.50	\$ -	\$ -	\$ -	\$ 57.50
Inspect Filtestep Kit	AAI Filtestep kit I/AW AA-01162 Rev E	Inspection	300	13812.7	42278	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	13812.7	42278	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
Lubricate Pitch change Mechanisim	I/AW Chptr12 Tbl 12-6	Inspection	300	13812.7	42278	\$ 10.00	\$ 42.50	\$ -	\$ -	\$ -	\$ 52.50
Periodic 300HR Inspection Events 1-6	I/AW Bel Helicopters MM Chptr 5-13 & 14	Inspection	300	13812.7	42278	\$ 200.00	\$ 3570.00	\$ -	\$ -	\$ -	\$ 3,770.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13812.7	42278	\$ -	\$ 85.00	\$ -	\$ -	\$ -	\$ 85.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	13812.7	42278	\$ -	\$ 85.00	\$ -	\$ -	\$ -	\$ 85.00
Tail Boom Inspection IAW ASB 407-08-84	Insp T/Boom 407-030-801-201.203 & 205	Inspection	300	13812.7	42278	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Torque Check T/R Mast nut	I/AW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	13812.7	42278	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13862.6	42309	\$ 50.00	\$ 170.00	\$ -	\$ -	\$ -	\$ 220.00
Lubricate Pitch change Mechanisim	I/AW Chptr12 Tbl 12-6	Inspection	3	13900	42339	\$ 10.00	\$ 42.50	\$ -	\$ -	\$ -	\$ 52.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13912.6	42339	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
100HR/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13912.6	42339	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13912.6	42339	\$ 50.00	\$ 170.00	\$ -	\$ -	\$ -	\$ 220.00
Insp/Lube T/R D/S Splines	I/AW Chptr 12 Tbl 12-1	Inspection	100	13912.6	42339	\$ 25.00	\$ 255.00	\$ -	\$ -	\$ -	\$ 280.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13912.6	42339	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	12	13955	42370	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
100HR/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	6	13955	42370	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13962.6	42370	\$ 50.00	\$ 170.00	\$ -	\$ -	\$ -	\$ 220.00
C/W 150 Hr Engine Inspection	I/AW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13962.7	42370	\$ -	\$ 170.00	\$ -	\$ -	\$ -	\$ 170.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Insp Upper Left Longeron	Inspection	150	13962.7	42370	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13962.7	42370	\$ -	\$ 85.00	\$ -	\$ -	\$ -	\$ 85.00
407-010-201-105	L/H Beam (Blue)	Retire	5000	13986.7	42370	\$ 8,020.00	\$ 1,020.00	\$ 100.00	\$ 25.50	\$ 25.50	\$ 9,165.50
407-010-203-105	R/H Beam (White)	Retire	5000	13986.7	42370	\$ 7,949.00	\$ 1,020.00	\$ 100.00	\$ 25.50	\$ 25.50	\$ 9,094.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	14012.6	42401	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
100HR/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	14012.6	42401	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	14012.6	42401	\$ 51.50	\$ 170.00	\$ -	\$ -	\$ -	\$ 221.50
Insp/Lube T/R D/S Splines	I/AW Chptr 12 Tbl 12-1	Inspection	100	14012.6	42401	\$ 25.75	\$ 255.00	\$ -	\$ -	\$ -	\$ 280.75
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	14012.6	42401	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	14063.5	42401	\$ 51.50	\$ 170.00	\$ -	\$ -	\$ -	\$ 221.50
406-040-500-131FM	Freewheel	Overhaul	2500	14063.5	42401	\$ 2,451.04	\$ 2,040.00	\$ 400.00	\$ 51.00	\$ 51.00	\$ 4,942.04
Lubricate Pitch change Mechanisim	I/AW Chptr12 Tbl 12-6	Inspection	3	14064.9	42430	\$ 10.30	\$ 42.50	\$ -	\$ -	\$ -	\$ 52.80
407-340-318-101	Rotor Brake Disk	Inspection	600	14077.2	42430	\$ -	\$ 340.00	\$ -	\$ 25.50	\$ 25.50	\$ 365.50
600 hr/12 month m/r blade insp.	I/AW Chptr 5-21	Inspection	600	14077.2	42430	\$ -	\$ 255.00	\$ -	\$ -	\$ -	\$ 255.00
Change Eng Oil with Royco 560	I/AW Rolls Royce Series MM Chptr 72 Tbl 604	Inspection	600	14077.2	42430	\$ 103.00	\$ 42.50	\$ -	\$ -	\$ -	\$ 145.50
Inspect Rotor Brake Assy	I/AW 600 Hr Inspection Chptr 5-20	Inspection	600	14077.2	42430	\$ -	\$ 340.00	\$ -	\$ -	\$ -	\$ 340.00
Inspection Of M/R Mast	Insp M/R mast IAW ASB 407-11-94	Inspection	600	14077.2	42430	\$ -	\$ 170.00	\$ -	\$ -	\$ -	\$ 170.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	14112.6	42430	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
100HR/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	14112.6	42430	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	14112.6	42430	\$ 51.50	\$ 170.00	\$ -	\$ -	\$ -	\$ 221.50
Insp/Lube T/R D/S Splines	I/AW Chptr 12 Tbl 12-1	Inspection	100	14112.6	42430	\$ 25.75	\$ 255.00	\$ -	\$ -	\$ -	\$ 280.75
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	14112.6	42430	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
300 HR Engine Inspection	I/AW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	14112.7	42430	\$ 103.00	\$ 850.00	\$ -	\$ -	\$ -	\$ 953.00
300 Hr/Annual Pedal Extension Insp	I/AW Paravion Technology ICA PR-407PX-120M	Inspection	300	14112.7	42430	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
300 HR/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	14112.7	42430	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
300HR Search Light Insp	I/AW S10899-01A	Inspection	300	14112.7	42430	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
ASB 407-14-106	Freewheel Oil Supply Blockage	Inspection	300	14112.7	42430	\$ 15.45	\$ 127.50	\$ -	\$ -	\$ -	\$ 142.95
C/W 150 Hr Engine Inspection	I/AW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	14112.7	42430	\$ -	\$ 170.00	\$ -	\$ -	\$ -	\$ 170.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Insp Upper Left Longeron	Inspection	150	14112.7	42430	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Change M/R Xmsn Oil with Royco 555 & M/R Filter	I/AW Chptr 12 Tbl 12-3	Inspection	300	14112.7	42430	\$ 103.00	\$ 85.00	\$ -	\$ -	\$ -	\$ 188.00
Change T/R/G/B Oil with Royco 555	I/AW Chptr 12 Tbl 12-3	Inspection	300	14112.7	42430	\$ 15.45	\$ 42.50	\$ -	\$ -	\$ -	\$ 57.95

Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	14112.7	42430	\$ 77.25	\$ 42.50	\$ -	\$ -	\$ -	\$ 119.75
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	14112.7	42430	\$ 51.50	\$ 127.50	\$ -	\$ -	\$ -	\$ 179.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	14112.7	42430	\$ 15.45	\$ 42.50	\$ -	\$ -	\$ -	\$ 57.95
Inspect Filtestep Kit	AAI Filtestep Kit IAW AA-01162 Rev E	Inspection	300	14112.7	42430	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	14112.7	42430	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
Lubricate Pitch change Mechanisim	IAW Chptr12 Tbl 12-6	Inspection	300	14112.7	42430	\$ 10.30	\$ 42.50	\$ -	\$ -	\$ -	\$ 52.80
Periodic 300Hr Inspection Events 1-6	IAW Bel Helicopters MM Chptr 5-13 & 14	Inspection	300	14112.7	42430	\$ 206.00	\$ 3,570.00	\$ -	\$ -	\$ -	\$ 3,776.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	14112.7	42430	\$ -	\$ 85.00	\$ -	\$ -	\$ -	\$ 85.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	14112.7	42430	\$ -	\$ 85.00	\$ -	\$ -	\$ -	\$ 85.00
Tail Boom Inspection IAW ASB 407-08-84	Insp T/Boom 407-030-801-201 203 & 205	Inspection	300	14112.7	42430	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	14112.7	42430	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
12 Month Inspection	IAW Chptr 5-22	Inspection	12	14119.8	42461	\$ -	\$ 510.00	\$ -	\$ -	\$ -	\$ 510.00
300HR Search Light Insp	IAW S10899-01A	Inspection	6	14119.8	42461	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
600 hr/12 month m/r blade insp.	IAW Chptr 5-21	Inspection	12	14119.8	42461	\$ -	\$ 255.00	\$ -	\$ -	\$ -	\$ 255.00
Annual Pulselite Insp	IAW Precise Flight Doc:000Pman0002	Inspection	12	14119.8	42461	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Bleedair Heater Insp	IAW ICA Aircomm 407H-200M-1	Inspection	12	14119.8	42461	\$ -	\$ 85.00	\$ -	\$ -	\$ -	\$ 85.00
Change Eng Oil with Royco 560	IAW Rolls Royce Series MM Chptr 72 Tbl 604	Inspection	12	14119.8	42461	\$ 103.00	\$ 42.50	\$ -	\$ -	\$ -	\$ 145.50
ELT Operation & Inspection	IAW FAR 91.207(d)	Inspection	12	14119.8	42461	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
Hydraulic By-pass Spool Inspection	Inspect hydraulic servo by-pass spool IAW BHT-407-N	Inspection	24	14119.8	42461	\$ -	\$ 255.00	\$ -	\$ -	\$ -	\$ 255.00
Hydraulic Servo Clevis Insp.	Inspect hydraulic servo clevis IAW BHT-407-MM	Inspection	12	14119.8	42461	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Inspect Fuel System	IAW Chptr 5-23	Inspection	24	14119.8	42461	\$ 51.50	\$ 595.00	\$ -	\$ -	\$ -	\$ 646.50
Inspection Of M/R Mast	Inspect M/R mast IAW ASB 407-11-94	Inspection	12	14119.8	42461	\$ -	\$ 170.00	\$ -	\$ -	\$ -	\$ 170.00
M/R Flight Control Bolts	IAW Chptr 5-23	Inspection	24	14119.8	42461	\$ -	\$ 1,020.00	\$ -	\$ -	\$ -	\$ 1,020.00
Mast Pole Inspection	IAW Component interim Insp Tbl 5-4	Inspection	12	14119.8	42461	\$ -	\$ 85.00	\$ -	\$ -	\$ -	\$ 85.00
Pitot Static Sys & Altimeter	IAW FAR 91.411(a)	Inspection	24	14119.8	42461	\$ -	\$ 340.00	\$ -	\$ -	\$ -	\$ 340.00
Spring Link Assy	IAW Chptr 5-23	Inspection	24	14119.8	42461	\$ -	\$ 510.00	\$ -	\$ -	\$ -	\$ 510.00
Transponder Biennial Check	IAW FAR 91.413(a)	Inspection	24	14119.8	42461	\$ -	\$ 85.00	\$ -	\$ -	\$ -	\$ 85.00
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	14162.6	42461	\$ 51.50	\$ 170.00	\$ -	\$ -	\$ -	\$ 221.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	14212.6	42491	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	14212.6	42491	\$ -	\$ 21.25	\$ -	\$ -	\$ -	\$ 21.25
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	14212.6	42491	\$ 51.50	\$ 170.00	\$ -	\$ -	\$ -	\$ 221.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	14212.6	42491	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	14212.6	42491	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Lubricate Pitch change Mechanisim	IAW Chptr12 Tbl 12-6	Inspection	3	14229.7	42522	\$ 10.30	\$ 42.50	\$ -	\$ -	\$ -	\$ 52.80
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	14262.6	42522	\$ 51.50	\$ 170.00	\$ -	\$ -	\$ -	\$ 221.50
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	14262.7	42522	\$ -	\$ 170.00	\$ -	\$ -	\$ -	\$ 170.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	150	14262.7	42522	\$ -	\$ 42.50	\$ -	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	14262.7	42522	\$ -	\$ 85.00	\$ -	\$ -	\$ -	\$ 85.00
23081-018	Starter Gen	Overhaul	1000	14278.7	42522	\$ 1,866.36	\$ 85.00	\$ 50.00	\$ 25.50	\$ -	\$ 2,026.86

**Total** \$ 56,396.78