## Landmark Designation Application (Continuation Sheets) – Page 25

## 11. Photographs

Attach at least four (4) 5x7 or larger color photographs showing the views of the property from the public right of way(s) and any important features or details. If available, attach copies of historic photographs of the structure.



1. 2600 N. Milwaukee St., southern wing. Facing northeast. Image by Paul Brokering, 2018.



2. 2600 N. Milwaukee St., south façade and southern wing. Facing north. Image by Shannon Schaefer Stage, March 2018.



3. 2600 N. Milwaukee St., detached garage on the western side of the property. Facing east. Image by Shannon Schaefer Stage, March 2018.



4. 2600 N. Milwaukee St., view of the southern wing's western end. Facing east. Image by Paul Brokering, 2018.



5. 2600 N. Milwaukee St., southern wing western entry and corner windows in western wing. Image by Shannon Schaefer Stage, March 2018.



6. Western entry with artwork seen through the windows, including sash weights to the left of the entry. Facing east. Image by Shannon Schaefer Stage, February 2018.



7. 2600 N. Milwaukee St., western wing facing southwest. Image by Shannon Schaefer Stage, March 2018.



8. 2600 N. Milwaukee St., west façade corner window with


Christmas decorations by the Henderson Family. Source: Henderson Family photograph collection, date unknown




9. 2600 N. Milwaukee St., western entry way. Source: Henderson Family photograph collection, date unknown



10. 1960 aerial image of City Park and City Park Golf Course, as well as the homes to the north, including 2600 N. Milwaukee St. The red arrow points to the empty plot of land that existed two years before the Hendersons bought the land. Source: Denver Public Library.



11. Historic Landmarks & Districts in the neighborhood surrounding City Park. Source: <a href="https://www.denvergov.org/maps/maps/maps/historiclandmarks">https://www.denvergov.org/maps/maps/historiclandmarks</a>



## Credential Information

License Number	License Method	License Type	License Status	Original Issue Date	Effective Date	Expiration Date
ARC.00300340	Reciprocity	Architect	Expired	10/07/1959	08/01/2007	07/31/2009

## **Board/Program Actions**

Discipline

There is no Discipline or Board Actions on file for this credential.

12. John R Henderson's Architect license online documentation. Original issue date on 10/7/1959. Source: https://apps.colorado.gov/dora/licensing/Lookup/LicenseLookup.aspx.