

FOURTH AMENDATORY AGREEMENT

THIS FOURTH AMENDATORY AGREEMENT is made between the **CITY AND COUNTY OF DENVER**, a municipal corporation of the State of Colorado (“City”) and **CENTURY HELICOPTERS, INC.**, a Colorado corporation, whose address is 2001 Airway Avenue, Fort Collins, Colorado 80524 (“Contractor”), collectively the “Parties”.

WITNESSETH:

WHEREAS, the City and the Contractor entered into an Agreement dated September 5, 2006, and amended the Agreement on August 7, 2007, June 16, 2009, and July 11, 2011, relating to scheduled and non-scheduled maintenance of the Denver Police Department’s helicopter for the purpose of maintaining optimal air worthiness status (the “Agreement”); and

WHEREAS, the Parties desire to amend the Agreement, to extend the term, increase the compensation to the Contractor and update other contract language.

NOW, THEREFORE, in consideration of the premises and the mutual covenants and obligations herein set forth, the Parties agree as follows:

1. Article 1 of the Agreement, **WORK TO BE PERFORMED**, is amended by the addition of the following paragraph at the end of the Article:

“In addition to the services previously described herein, for the period of time from June 1, 2013 through June 30, 2015, the Contractor agrees to provide the services at the rates and costs set out forth in **Exhibit A-4**, attached hereto and incorporated herein by this reference. The Contractor agrees to provide these services in a workman like manner, consistent with the manufacturer’s instructions and recommendations and the terms and conditions of the Agreement.”

2. Article 3 of the Agreement, entitled “**TERM OF AGREEMENT**”, is hereby amended to read as follows:

“**3. TERM OF AGREEMENT**: The term of the Agreement shall commence on June 1, 2006 and terminate on June 30, 2015 unless otherwise terminated earlier under the terms of this Agreement.”

3. The first, second, third and fourth sentences of Article 5 of the Agreement, entitled “**COMPENSATION AND PAYMENT**,” are hereby amended to read as follows:

“**5. COMPENSATION AND PAYMENT**: The Contractor agrees to accept, and the City agrees to pay, as full and complete compensation for completion of all the items of work contained in the Agreement and the Exhibits attached thereto, including **Exhibit A-4**, for the period of time from June 1, 2006 through

June 30, 2015, a total sum not to exceed **TWO MILLION EIGHT HUNDRED FORTY EIGHT THOUSAND NINE HUNDRED EIGHTY TWO DOLLARS AND NINETY FOUR CENTS (\$2,848,982.94)** (“**Maximum Contract Amount**”), which for this amendment is funded through the City’s receipt of a grant and yearly appropriation requests are subject to the City’s receipt of said grant funds. Compensation shall be payable at the rate of **Eighty-Five Dollars (\$85.00)** per hour regular rate (**work performed on Monday through Friday, 8:00 a.m to 5:00 p.m., excluding federal holidays**) or **One Hundred Twenty-Seven Dollars and Fifty Cents (\$127.50)** per hour overtime rate (**work performed at all other days and times**), as applicable, for services, and on the basis of Bell Helicopter price lists approved by the City for parts and materials, payable upon receipt and approval by the City of complete and satisfactory invoices from the Contractor, demonstrating performance of services. It is understood and agreed that the process specified in the Bell Helicopter Textron 2011, 2012, 2013, 2014 and 2015 price list shall apply to those respective years. The 2011, 2012, 2013, 2014 and 2015 price lists are incorporated into this Agreement by reference.”

4. Except as herein amended, the Agreement is affirmed and ratified in each and every particular.

6. This Fourth Amendatory Agreement may be executed in counterparts, each of which is an original and constitute the same instrument.

[BALANCE OF PAGE INTENTIONALLY LEFT BLANK]

Contract Control Number: POLIC-CE61220-04

Contractor Name: CENTURY HELICOPTERS INC

By: 

Name: Michael E. Hansen
(please print)

Title: General Manager
(please print)

ATTEST: [if required]

By: _____

Name: _____
(please print)

Title: _____
(please print)



Contract Control Number:

IN WITNESS WHEREOF, the parties have set their hands and affixed their seals at Denver, Colorado as of

SEAL

CITY AND COUNTY OF DENVER

ATTEST:

By _____

APPROVED AS TO FORM:

REGISTERED AND COUNTERSIGNED:

By _____

By _____

By _____



Exhibit A-4

(Exhibit on Following Page)

This contract amendment will cover any rate increases; previously uncovered timeframe for unit inspections, maintenance, and major overhauls through the period of June 30, 2015.

The quote generated in March 2013 is in many areas duplicative of timeframes that have already been quoted in the contract period of June 1, 2011 through May 31, 2013; therefore only the price increase and any scheduled service beyond the 13,000 hour mark need be included in the fourth amendment to the contract.

Price increase (Hours 12,249.8 – 13,000)	\$161,421.01
New defined service period (Hours 13,003.8 – 13,653.8)	\$ 47,315.49
Rental Cost (Hours 13,003.8 – 13,653.8)	\$ 35,900.00
Installation of Garmin 796	\$ 3,800.00
Shipping	\$ 5,000.00
On Board Equipment Cost (June 1, 2013 – June 30, 2015)	\$ 45,000.00
On Condition Equipment Cost (June 1, 2013 – June 30, 2015)	\$ 45,000.00
Contingency Cost 10%	<u>\$ 33,963.65</u>
TOTAL CONTRACT AMENDMENT	\$377,400.15

Aircraft Projection Report

Aircraft Registration	N710DP	Labor Rate	\$ 85.00
Aircraft Serial Number	53249	Admin Rate	\$ -
Date Report Generated	3/22/3012	Misc Rate	\$ -
Projection Start Hours	12241.2	Parts Increase	0%
Projection Start Date	3/15/2013		
Projection End Hours	12413.1		
Projection End Date	5/31/2013		

Item	Description	Limit Type	Limit	Time Due	Date Due	Parts	Labor	Misc	Admin	Total
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12249.8	Feb-13	\$ 100.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,245.00
Inspect Rotor Brake Assy	IAW 600 Hr Inspection Chptr 5-20	Inspection	600	12250	Feb-13	\$ 25.00	\$ 170.00	\$ -	\$ -	\$ 195.00
Progressive inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	300	12250	Feb-13	\$ 200.00	\$ 3,400.00	\$ -	\$ -	\$ 3,600.00
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	12250	Feb-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	12250	Feb-13	\$ 600.00	\$ 85.00	\$ -	\$ -	\$ 685.00
Tailboom Inspection	Insp Tailboom 407-030-801-205 Per Fig 4-5	Inspection	300	12250	Feb-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	12250	Feb-13	\$ 100.00	\$ 85.00	\$ -	\$ -	\$ 185.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	12250	Feb-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	12250	Feb-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	12250	Feb-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Inspect Flitestep Kit	AAI Flitesteo kit IAW AA-01162 Rev E	Inspection	300	12250	Feb-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	12250	Feb-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	12250	Feb-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	12250	Feb-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	12250	Feb-13	\$ 25.00	\$ 42.50	\$ -	\$ -	\$ 67.50
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	12250	Feb-13	\$ 75.00	\$ 1,360.00	\$ -	\$ -	\$ 1,435.00
407-340-318-101	Rotor Brake Disk	Inspection	600	12250	Feb-13	\$ -	\$ 340.00	\$ -	\$ -	\$ 340.00
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12253.8	Feb-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12253.8	Feb-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12303.8	Mar-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12303.8	Mar-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12303.8	Mar-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12303.8	Mar-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12303.8	Mar-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12303.8	Mar-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Mast Pole Inspection	IAW Component Interim Insp Tbl 5-4	Inspection	12	12307.4	Apr-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
ELT Operation & Inspection	IAW FAR 91.207(d)	Inspection	12	12307.4	Apr-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	12	12307.4	Apr-13	\$ 100.00	\$ 85.00	\$ -	\$ -	\$ 185.00
12 Month Inspection	IAW Chptr 5-22	Inspection	12	12307.4	Apr-13	\$ 300.00	\$ 680.00	\$ -	\$ -	\$ 980.00
Bleedair Heater Insp	IAW ICA Aircomm 407H-200M-1	Inspection	12	12307.4	Apr-13	\$ -	\$ 340.00	\$ -	\$ -	\$ 340.00
Annual Pulselite Insp	IAW Precise Flight Doc:000Pman0002	Inspection	12	12307.4	Apr-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
600 hr/12 month m/r blade insp.	IAW Chptr 5-21	Inspection	12	12307.4	Apr-13	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
Inspection Of M/R Mast	Inspect M/R mast IAW ASB 407-11-94	Inspection	12	12307.4	Apr-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Hydraulic Servo Clevis Insp.	Inspect hydraulic servo clevis IAW BHT-407-MM	Inspection	12	12307.4	Apr-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	12353.8	Apr-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12353.8	Apr-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12353.8	Apr-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
407-010-100-115	Hub Assy Mr	Overhaul	2500	12379.7	May-13	\$ -	\$ 6,800.00	\$ -	\$ -	\$ 6,800.00
406-010-115-127	Upper Plate	Retire	2500	12379.7	May-13	\$ 7,669.00	\$ -	\$ -	\$ -	\$ 7,669.00
406-010-117-125	Lower Plate	Retire	2500	12379.7	May-13	\$ 6,143.00	\$ -	\$ -	\$ -	\$ 6,143.00
407-040-011-107	Mast Assy	Overhaul	2500	12379.7	May-13	\$ 900.00	\$ 1,700.00	\$ -	\$ -	\$ 2,600.00
406-010-401-117	Swashplate & Support	Overhaul	2500	12379.7	May-13	\$ 1,000.00	\$ 5,525.00	\$ -	\$ -	\$ 6,525.00
407-012-101-107	Hub Assy Tr	Overhaul	2500	12379.7	May-13	\$ -	\$ 1,700.00	\$ -	\$ -	\$ 1,700.00
406-010-413-131	Pitch Link Assy(Red)	Inspection	2500	12379.7	May-13	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00

406-010-413-131	Pitch Link Assy (Or)	Inspection	2500	12379.7	May-13	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
406-010-413-131	Pitch Link Assy (Bl)	Inspection	2500	12379.7	May-13	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
406-010-413-131	Pitch Link Assy (Gr)	Inspection	2500	12379.7	May-13	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
300HR Search Light Insp	IAW SI0899-01A	Inspection	300	12399.8	May-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12399.8	May-13	\$ 100.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,245.00
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12403.8	May-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12403.8	May-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12403.8	May-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12403.8	May-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12403.8	May-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12403.8	May-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
406-040-400-117FM	Gearbox Tr	Overhaul	5000	12413.1	Jun-13	\$ 1,000.00	\$ 2,720.00	\$ -	\$ -	\$ 3,720.00

Total

\$ 49,389.50

Aircraft Projection Report

Aircraft Registration	N710DP	Labor Rate	\$ 85.00
Aircraft Serial Number	53249	Admin Rate	\$ -
Date Report Generated	2/25/2013	Misc Rate	\$ -
Projection Start Hours	12413.1	Parts Increase	3%
Projection Start Date	6/1/2013		
Projection End Hours	13653.8		
Projection End Date	5/31/2015		

Item	Description	Limit Type	Limit	Time Due	Date Due	Parts	Labor	Misc	Admin	Total
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12453.8	Jun-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12453.8	Jun-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300HR Search Light Insp	IAW SJ0899-01A	Inspection	6	12462.7	Jul-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
23063354	Turbine Assy	Overhaul	2000	12500	Jul-13	\$ 110,000.00	\$ 5,440.00	\$ 1,000.00	\$ -	\$ 116,440.00
23065593	Compressor	Inspection	2000	12500	Jul-13	\$ 40,000.00	\$ -	\$ -	\$ -	\$ 40,000.00
C/W 2000 hr Engine Inspection	IAW Rolls Royce Series MM Chptr 72 tbl 605	Inspection	2000	12500	Jul-13	\$ -	\$ -	\$ 10,000.00	\$ -	\$ 10,000.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12503.8	Jul-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12503.8	Jul-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12503.8	Jul-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12503.8	Jul-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12503.8	Jul-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12503.8	Jul-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	12503.8	Jul-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
23032280	Turbine/2Nd Stg	Retire	2025	12525	Aug-13	\$ 20,000.00	\$ 42.50	\$ -	\$ -	\$ 20,042.50
23053299	Turbine/1St Stg	Retire	2025	12525	Aug-13	\$ 20,000.00	\$ 42.50	\$ -	\$ -	\$ 20,042.50
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12549.8	Aug-13	\$ 100.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,245.00
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	12550	Aug-13	\$ 75.00	\$ 1,360.00	\$ -	\$ -	\$ 1,435.00
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	12550	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	12550	Aug-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	12550	Aug-13	\$ 100.00	\$ 85.00	\$ -	\$ -	\$ 185.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	12550	Aug-13	\$ 25.00	\$ 42.50	\$ -	\$ -	\$ 67.50
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	12550	Aug-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	12550	Aug-13	\$ 600.00	\$ 85.00	\$ -	\$ -	\$ 685.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	12550	Aug-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect Flitestep Kit	AAI Flitestep kit IAW AA-01162 Rev E	Inspection	300	12550	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	12550	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Progressive inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	300	12550	Aug-13	\$ 200.00	\$ 3,400.00	\$ -	\$ -	\$ 3,600.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	12550	Aug-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
T/R Pitch Change Control Tube	IAW Chptr 5-24	Inspection	1200	12550	Aug-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Tailboom Inspection	Insp Tailboom 407-030-801-205 Per Fig 4-5	Inspection	300	12550	Aug-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	12550	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12553.8	Aug-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12553.8	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	6	12566.3	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
206-340-300-107	Input Driveshaft	Overhaul	1250	12600	Sep-13	\$ -	\$ 340.00	\$ 25,000.00	\$ -	\$ 25,340.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12603.8	Sep-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12603.8	Sep-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12603.8	Sep-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12603.8	Sep-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12603.8	Sep-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12603.8	Sep-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	12	12618.1	Oct-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	12	12618.1	Oct-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	12	12618.1	Oct-13	\$ 25.00	\$ 42.50	\$ -	\$ -	\$ 67.50

Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	12	12618.1	Oct-13	\$ 600.00	\$ 85.00	\$ -	\$ -	\$ 685.00
Inspect Flitstep Kit	AAI Flitstep kit IAW AA-01162 Rev E	Inspection	12	12618.1	Oct-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	12	12618.1	Oct-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Progressive inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	12	12618.1	Oct-13	\$ 200.00	\$ 3,400.00	\$ -	\$ -	\$ 3,600.00
23081-018	Starter Gen	Overhaul	1000	12650	Oct-13	\$ 2,500.00	\$ 85.00	\$ -	\$ -	\$ 2,585.00
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12653.8	Oct-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12653.8	Oct-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	12653.8	Oct-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
T/R Pitch Change Control Tube	IAW Chptr 5-24	Inspection	24	12669.9	Nov-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
300HR Search Light Insp	IAW SI0899-01A	Inspection	300	12699.8	Nov-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12699.8	Nov-13	\$ 100.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,245.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12703.8	Nov-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12703.8	Nov-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12703.8	Nov-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12703.8	Nov-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12703.8	Nov-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12703.8	Nov-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12753.8	Dec-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12753.8	Dec-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
600 hr/12 month m/r blade insp.	IAW Chptr 5-21	Inspection	600	12763.5	Dec-13	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
Inspection Of M/R Mast	Inspect M/R mast IAW ASB 407-11-94	Inspection	600	12763.5	Dec-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
407-040-011-107	Mast Assy	Inspection	60	12773.4	Jan-14	\$ -	\$ 850.00	\$ -	\$ -	\$ 850.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12803.8	Jan-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12803.8	Jan-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12803.8	Jan-14	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12803.8	Jan-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change Eng Oil with Royco 560	IAW Rolls Royce Series MM Chptr 72 Tbl 604	Inspection	600	12803.8	Jan-14	\$ 300.00	\$ 85.00	\$ -	\$ -	\$ 385.00
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12803.8	Jan-14	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12803.8	Jan-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	12803.8	Jan-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12849.8	Feb-14	\$ 103.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,248.00
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	12850	Feb-14	\$ 77.25	\$ 1,360.00	\$ -	\$ -	\$ 1,437.25
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	12850	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	12850	Feb-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
407-340-318-101	Rotor Brake Disk	Inspection	600	12850	Feb-14	\$ -	\$ 340.00	\$ -	\$ -	\$ 340.00
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	12850	Feb-14	\$ 103.00	\$ 85.00	\$ -	\$ -	\$ 188.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	12850	Feb-14	\$ 25.75	\$ 42.50	\$ -	\$ -	\$ 68.25
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	12850	Feb-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	12850	Feb-14	\$ 618.00	\$ 85.00	\$ -	\$ -	\$ 703.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	12850	Feb-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect Flitstep Kit	AAI Flitstep kit IAW AA-01162 Rev E	Inspection	300	12850	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect Rotor Brake Assy	IAW 600 Hr Inspection Chptr 5-20	Inspection	600	12850	Feb-14	\$ 25.75	\$ 170.00	\$ -	\$ -	\$ 195.75
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	12850	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Progressive inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	300	12850	Feb-14	\$ 206.00	\$ 3,400.00	\$ -	\$ -	\$ 3,606.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	12850	Feb-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Tailboom Inspection	Insp Tailboom 407-030-801-205 Per Fig 4-5	Inspection	300	12850	Feb-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	12850	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12853.8	Feb-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12853.8	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	12	12877	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change Eng Oil with Royco 560	IAW Rolls Royce Series MM Chptr 72 Tbl 604	Inspection	12	12877	Feb-14	\$ 309.00	\$ 85.00	\$ -	\$ -	\$ 394.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12903.8	Mar-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12903.8	Mar-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12903.8	Mar-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12903.8	Mar-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12903.8	Mar-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12903.8	Mar-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50

21716	Gimbal Arms	Retire	84	12928.8	Mar-14	\$ 20,600.00	\$ 340.00	\$ 100.00	\$ -	\$ 21,040.00
Hydraulic By-pass Spool Inspection	Inspect hydraulic servo by-pass spool IAW BHT-407-MM	Inspection	24	12928.8	Apr-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Inspect Fuel System	IAW Chptr 5-23	Inspection	24	12928.8	Apr-14	\$ -	\$ 510.00	\$ -	\$ -	\$ 510.00
M/R Flight Control Bolts	IAW Chptr 5-23	Inspection	24	12928.8	Apr-14	\$ -	\$ 510.00	\$ -	\$ -	\$ 510.00
Pitot Static Sys & Altimeter	IAW FAR 91.411(a)	Inspection	24	12928.8	Apr-14	\$ -	\$ 510.00	\$ -	\$ -	\$ 510.00
Spring Link Assy	IAW Chptr 5-23	Inspection	24	12928.8	Apr-14	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
Transponder Biennial Check	IAW FAR 91.413(a)	Inspection	24	12928.8	Apr-14	\$ -	\$ 340.00	\$ -	\$ -	\$ 340.00
206-340-300-107	Input Driveshaft	Retire	5000	12953.4	Apr-14	\$ 41,759.29	\$ 340.00	\$ 100.00	\$ -	\$ 42,199.29
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12953.8	Apr-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12953.8	Apr-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	12953.8	Apr-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
300HR Search Light Insp	IAW SIO899-01A	Inspection	300	12999.8	May-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12999.8	May-14	\$ 103.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,248.00
23078031	Hmu	Overhaul	2500	13000	May-14	\$ 37,080.00	\$ 510.00	\$ 50.00	\$ -	\$ 37,640.00
407-040-006-107FMS	Transmission	Overhaul	4500	13000	May-14	\$ 2,575.00	\$ 10,625.00	\$ 50.00	\$ -	\$ 13,250.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13003.8	May-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13003.8	May-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13003.8	May-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13003.8	May-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13003.8	May-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13003.8	May-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13053.8	Jun-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13053.8	Jun-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
23073353	Bleed Valve	Overhaul	1500	13063.5	Jun-14	\$ 3,605.00	\$ 340.00	\$ 25.00	\$ -	\$ 3,970.00
Replace ELT Batetry	IAW FAR 91.207(d)	Inspection	53	13084.2	Jul-14	\$ 257.50	\$ 85.00	\$ 25.00	\$ -	\$ 367.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13103.8	Jul-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13103.8	Jul-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13103.8	Jul-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13103.8	Jul-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13103.8	Jul-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13103.8	Jul-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13103.8	Jul-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13149.8	Aug-14	\$ 103.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,248.00
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	13150	Aug-14	\$ 77.25	\$ 1,360.00	\$ -	\$ -	\$ 1,437.25
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	13150	Aug-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	13150	Aug-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	13150	Aug-14	\$ 103.00	\$ 85.00	\$ -	\$ -	\$ 188.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	13150	Aug-14	\$ 25.75	\$ 42.50	\$ -	\$ -	\$ 68.25
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	13150	Aug-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	13150	Aug-14	\$ 618.00	\$ 85.00	\$ -	\$ -	\$ 703.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	13150	Aug-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect Flitestep Kit	AAI Flitestep kit IAW AA-01162 Rev E	Inspection	300	13150	Aug-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	13150	Aug-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Progressive inspection Events 1-6	IAW Bel Helicopters MM Chptr 5-13 & 14	Inspection	300	13150	Aug-14	\$ 206.00	\$ 3,400.00	\$ -	\$ -	\$ 3,606.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	13150	Aug-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Tailboom Inspection	Insp Tailboom 407-030-801-205 Per Fig 4-5	Inspection	300	13150	Aug-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	13150	Aug-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13153.8	Aug-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13153.8	Aug-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13203.8	Sep-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13203.8	Sep-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13203.8	Sep-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13203.8	Sep-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13203.8	Sep-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13203.8	Sep-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13253.8	Oct-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13253.8	Oct-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50

Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13253.8	Oct-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
300HR Search Light Insp	IAW SI0899-01A	Inspection	300	13299.8	Nov-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13299.8	Nov-14	\$ 103.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,248.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13303.8	Nov-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13303.8	Nov-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13303.8	Nov-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13303.8	Nov-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13303.8	Nov-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13303.8	Nov-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13353.8	Dec-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13353.8	Dec-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
600 hr/12 month m/r blade insp.	IAW Chptr 5-21	Inspection	600	13363.5	Dec-14	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
Inspection Of M/R Mast	Inspect M/R mast IAW ASB 407-11-94	Inspection	600	13363.5	Dec-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13403.8	Jan-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13403.8	Jan-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13403.8	Jan-15	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13403.8	Jan-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change Eng Oil with Royco 560	IAW Rolls Royce Series MM Chptr 72 Tbl 604	Inspection	600	13403.8	Jan-15	\$ 309.00	\$ 85.00	\$ -	\$ -	\$ 394.00
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13403.8	Jan-15	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13403.8	Jan-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13403.8	Jan-15	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13449.8	Feb-15	\$ 106.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,251.00
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	13450	Feb-15	\$ 79.50	\$ 1,360.00	\$ -	\$ -	\$ 1,439.50
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	13450	Feb-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	13450	Feb-15	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
407-340-302-101	Rotor Brake Caliper	Overhaul	1800	13450	Feb-15	\$ 3,710.00	\$ 850.00	\$ -	\$ -	\$ 4,560.00
407-340-302-101	Rotor Brake Caliper	Overhaul	1800	13450	Feb-15	\$ 3,710.00	\$ 850.00	\$ -	\$ -	\$ 4,560.00
407-340-318-101	Rotor Brake Disk	Inspection	600	13450	Feb-15	\$ -	\$ 340.00	\$ -	\$ -	\$ 340.00
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	13450	Feb-15	\$ 106.00	\$ 85.00	\$ -	\$ -	\$ 191.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	13450	Feb-15	\$ 26.50	\$ 42.50	\$ -	\$ -	\$ 69.00
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	13450	Feb-15	\$ 79.50	\$ 85.00	\$ -	\$ -	\$ 164.50
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	13450	Feb-15	\$ 636.00	\$ 85.00	\$ -	\$ -	\$ 721.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	13450	Feb-15	\$ 79.50	\$ 85.00	\$ -	\$ -	\$ 164.50
Inspect Flitstep Kit	AAI Flitstep kit IAW AA-01162 Rev E	Inspection	300	13450	Feb-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect Rotor Brake Assy	IAW 600 Hr Inspection Chptr 5-20	Inspection	600	13450	Feb-15	\$ 26.50	\$ 170.00	\$ -	\$ -	\$ 196.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	13450	Feb-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Progressive inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	300	13450	Feb-15	\$ 212.00	\$ 3,400.00	\$ -	\$ -	\$ 3,612.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	13450	Feb-15	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Tailboom Inspection	Insp Tailboom 407-030-801-205 Per Fig 4-5	Inspection	300	13450	Feb-15	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	13450	Feb-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13453.8	Feb-15	\$ 53.00	\$ 85.00	\$ -	\$ -	\$ 138.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13453.8	Feb-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13503.8	Mar-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13503.8	Mar-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13503.8	Mar-15	\$ 53.00	\$ 85.00	\$ -	\$ -	\$ 138.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13503.8	Mar-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13503.8	Mar-15	\$ 79.50	\$ 85.00	\$ -	\$ -	\$ 164.50
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13503.8	Mar-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13553.8	Apr-15	\$ 53.00	\$ 85.00	\$ -	\$ -	\$ 138.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13553.8	Apr-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13553.8	Apr-15	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
406-310-405-101	Bearing (Or)	Retire	5000	13595.4	Apr-15	\$ 2,839.74	\$ 170.00	\$ -	\$ -	\$ 3,009.74
300HR Search Light Insp	IAW SI0899-01A	Inspection	300	13599.8	Apr-15	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13599.8	Apr-15	\$ 106.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,251.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13603.8	May-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13603.8	May-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13603.8	May-15	\$ 53.00	\$ 85.00	\$ -	\$ -	\$ 138.00

C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13603.8	May-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13603.8	May-15	\$ 79.50	\$ 85.00	\$ -	\$ -	\$ 164.50
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13603.8	May-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
23077067	Fuel Nozzle	Overhaul	2000	13650	May-15	\$ 2,120.00	\$ 170.00	\$ 25.00	\$ -	\$ 2,315.00
23081-018	Starter Gen	Overhaul	1000	13650	May-15	\$ 2,650.00	\$ 85.00	\$ -	\$ -	\$ 2,735.00
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13653.8	Jun-15	\$ 53.00	\$ 85.00	\$ -	\$ -	\$ 138.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13653.8	Jun-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50

Total

\$ 429,236.78

Aircraft Projection Report										
Aircraft Registration	N710DP	Labor Rate	\$ 85.00							
Aircraft Serial Number	53249	Admin Rate	\$ -							
Date Report Generated	3/22/3012	Misc Rate	\$ -							
		Parts Increase	0%							
Projection Start Hours	12241.2									
Projection Start Date	3/15/2013									
Projection End Hours	12413.1									
Projection End Date	5/31/2013									
Item	Description	Limit Type	Limit	Time Due	Date Due	Parts	Labor	Misc	Admin	Total
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12249.8	Feb-13	\$ 100.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,245.00
Inspect Rotor Brake Assy	IAW 600 Hr Inspection Chptr 5-20	Inspection	600	12250	Feb-13	\$ 25.00	\$ 170.00	\$ -	\$ -	\$ 195.00
Progressive inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	300	12250	Feb-13	\$ 200.00	\$ 3,400.00	\$ -	\$ -	\$ 3,600.00
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	12250	Feb-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	12250	Feb-13	\$ 600.00	\$ 85.00	\$ -	\$ -	\$ 685.00
Tailboom Inspection	Insp Tailboom 407-030-801-205 Per Fig 4-5	Inspection	300	12250	Feb-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	12250	Feb-13	\$ 100.00	\$ 85.00	\$ -	\$ -	\$ 185.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	12250	Feb-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	12250	Feb-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	12250	Feb-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Inspect Flitestep Kit	AAI Flitestep kit IAW AA-01162 Rev E	Inspection	300	12250	Feb-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	12250	Feb-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	12250	Feb-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	12250	Feb-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	12250	Feb-13	\$ 25.00	\$ 42.50	\$ -	\$ -	\$ 67.50
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	12250	Feb-13	\$ 75.00	\$ 1,360.00	\$ -	\$ -	\$ 1,435.00
407-340-318-101	Rotor Brake Disk	Inspection	600	12250	Feb-13	\$ -	\$ 340.00	\$ -	\$ -	\$ 340.00
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12253.8	Feb-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12253.8	Feb-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12303.8	Mar-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12303.8	Mar-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12303.8	Mar-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12303.8	Mar-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12303.8	Mar-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12303.8	Mar-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Mast Pole Inspection	IAW Component Interim Insp Tbl 5-4	Inspection	12	12307.4	Apr-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
ELT Operation & Inspection	IAW FAR 91.207(d)	Inspection	12	12307.4	Apr-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	12	12307.4	Apr-13	\$ 100.00	\$ 85.00	\$ -	\$ -	\$ 185.00
12 Month Inspection	IAW Chptr 5-22	Inspection	12	12307.4	Apr-13	\$ 300.00	\$ 680.00	\$ -	\$ -	\$ 980.00
Bleedair Heater Insp	IAW ICA Aircomm 407H-200M-1	Inspection	12	12307.4	Apr-13	\$ -	\$ 340.00	\$ -	\$ -	\$ 340.00
Annual Pulselite Insp	IAW Precise Flight Doc:000Pman0002	Inspection	12	12307.4	Apr-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
600 hr/12 month m/r blade insp.	IAW Chptr 5-21	Inspection	12	12307.4	Apr-13	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
Inspection Of M/R Mast	Inspect M/R mast IAW ASB 407-11-94	Inspection	12	12307.4	Apr-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Hydraulic Servo Clevis Insp.	Inspect hydraulic servo clevis IAW BHT-407-MM	Inspection	12	12307.4	Apr-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	12353.8	Apr-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12353.8	Apr-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12353.8	Apr-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
407-010-100-115	Hub Assy Mr	Overhaul	2500	12379.7	May-13	\$ -	\$ 6,800.00	\$ -	\$ -	\$ 6,800.00
406-010-115-127	Upper Plate	Retire	2500	12379.7	May-13	\$ 7,669.00	\$ -	\$ -	\$ -	\$ 7,669.00
406-010-117-125	Lower Plate	Retire	2500	12379.7	May-13	\$ 6,143.00	\$ -	\$ -	\$ -	\$ 6,143.00
407-040-011-107	Mast Assy	Overhaul	2500	12379.7	May-13	\$ 900.00	\$ 1,700.00	\$ -	\$ -	\$ 2,600.00
406-010-401-117	Swashplate & Support	Overhaul	2500	12379.7	May-13	\$ 1,000.00	\$ 5,525.00	\$ -	\$ -	\$ 6,525.00
407-012-101-107	Hub Assy Tr	Overhaul	2500	12379.7	May-13	\$ -	\$ 1,700.00	\$ -	\$ -	\$ 1,700.00
406-010-413-131	Pitch Link Assy(Red)	Inspection	2500	12379.7	May-13	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00

Aircraft Projection Report										
Aircraft Registration	N710DP	Labor Rate	\$ 85.00							
Aircraft Serial Number	53249	Admin Rate	\$ -							
Date Report Generated	2/25/2013	Misc Rate	\$ -							
		Parts Increase	3%							
Projection Start Hours	12413.1									
Projection Start Date	6/1/2013									
Projection End Hours	13653.8									
Projection End Date	5/31/2015									
Item	Description	Limit Type	Limit	Time Due	Date Due	Parts	Labor	Misc	Admin	Total
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12453.8	Jun-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12453.8	Jun-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300HR Search Light Insp	IAW SJ0899-01A	Inspection	6	12462.7	Jul-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
23063354	Turbine Assy	Overhaul	2000	12500	Jul-13	\$ 110,000.00	\$ 5,440.00	\$ 1,000.00	\$ -	\$ 116,440.00
23065593	Compressor	Inspection	2000	12500	Jul-13	\$ 40,000.00	\$ -	\$ -	\$ -	\$ 40,000.00
C/W 2000 hr Engine Inspection	IAW Rolls Royce Series MM Chptr 72 tbl 605	Inspection	2000	12500	Jul-13	\$ -	\$ -	\$ 10,000.00	\$ -	\$ 10,000.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12503.8	Jul-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12503.8	Jul-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12503.8	Jul-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12503.8	Jul-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12503.8	Jul-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12503.8	Jul-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	12503.8	Jul-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
23032280	Turbine/2Nd Stg	Retire	2025	12525	Aug-13	\$ 20,000.00	\$ 42.50	\$ -	\$ -	\$ 20,042.50
23053299	Turbine/1St Stg	Retire	2025	12525	Aug-13	\$ 20,000.00	\$ 42.50	\$ -	\$ -	\$ 20,042.50
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12549.8	Aug-13	\$ 100.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,245.00
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	12550	Aug-13	\$ 75.00	\$ 1,360.00	\$ -	\$ -	\$ 1,435.00
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	12550	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	12550	Aug-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	12550	Aug-13	\$ 100.00	\$ 85.00	\$ -	\$ -	\$ 185.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	12550	Aug-13	\$ 25.00	\$ 42.50	\$ -	\$ -	\$ 67.50
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	12550	Aug-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	12550	Aug-13	\$ 600.00	\$ 85.00	\$ -	\$ -	\$ 685.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	12550	Aug-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect Flitstep Kit	AAI Flitstep kit IAW AA-01162 Rev E	Inspection	300	12550	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	12550	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Progressive inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	300	12550	Aug-13	\$ 200.00	\$ 3,400.00	\$ -	\$ -	\$ 3,600.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	12550	Aug-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
T/R Pitch Change Control Tube	IAW Chptr 5-24	Inspection	1200	12550	Aug-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Tailboom Inspection	Insp Tailboom 407-030-801-205 Per Fig 4-5	Inspection	300	12550	Aug-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	12550	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12553.8	Aug-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12553.8	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	6	12566.3	Aug-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
206-340-300-107	Input Driveshaft	Overhaul	1250	12600	Sep-13	\$ -	\$ 340.00	\$ 25,000.00	\$ -	\$ 25,340.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12603.8	Sep-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12603.8	Sep-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12603.8	Sep-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12603.8	Sep-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12603.8	Sep-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12603.8	Sep-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	12	12618.1	Oct-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	12	12618.1	Oct-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	12	12618.1	Oct-13	\$ 25.00	\$ 42.50	\$ -	\$ -	\$ 67.50

Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	12	12618.1	Oct-13	\$ 600.00	\$ 85.00	\$ -	\$ -	\$ 685.00
Inspect Flitstep Kit	AAI Flitstep kit IAW AA-01162 Rev E	Inspection	12	12618.1	Oct-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	12	12618.1	Oct-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Progressive inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	12	12618.1	Oct-13	\$ 200.00	\$ 3,400.00	\$ -	\$ -	\$ 3,600.00
23081-018	Starter Gen	Overhaul	1000	12650	Oct-13	\$ 2,500.00	\$ 85.00	\$ -	\$ -	\$ 2,585.00
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12653.8	Oct-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12653.8	Oct-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	12653.8	Oct-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
T/R Pitch Change Control Tube	IAW Chptr 5-24	Inspection	24	12669.9	Nov-13	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
300HR Search Light Insp	IAW SI0899-01A	Inspection	300	12699.8	Nov-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12699.8	Nov-13	\$ 100.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,245.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12703.8	Nov-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12703.8	Nov-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12703.8	Nov-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12703.8	Nov-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12703.8	Nov-13	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12703.8	Nov-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12753.8	Dec-13	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12753.8	Dec-13	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
600 hr/12 month m/r blade insp.	IAW Chptr 5-21	Inspection	600	12763.5	Dec-13	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
Inspection Of M/R Mast	Inspect M/R mast IAW ASB 407-11-94	Inspection	600	12763.5	Dec-13	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
407-040-011-107	Mast Assy	Inspection	60	12773.4	Jan-14	\$ -	\$ 850.00	\$ -	\$ -	\$ 850.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12803.8	Jan-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12803.8	Jan-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12803.8	Jan-14	\$ 50.00	\$ 85.00	\$ -	\$ -	\$ 135.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12803.8	Jan-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change Eng Oil with Royco 560	IAW Rolls Royce Series MM Chptr 72 Tbl 604	Inspection	600	12803.8	Jan-14	\$ 300.00	\$ 85.00	\$ -	\$ -	\$ 385.00
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12803.8	Jan-14	\$ 75.00	\$ 85.00	\$ -	\$ -	\$ 160.00
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12803.8	Jan-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	12803.8	Jan-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12849.8	Feb-14	\$ 103.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,248.00
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	12850	Feb-14	\$ 77.25	\$ 1,360.00	\$ -	\$ -	\$ 1,437.25
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	12850	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	12850	Feb-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
407-340-318-101	Rotor Brake Disk	Inspection	600	12850	Feb-14	\$ -	\$ 340.00	\$ -	\$ -	\$ 340.00
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	12850	Feb-14	\$ 103.00	\$ 85.00	\$ -	\$ -	\$ 188.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	12850	Feb-14	\$ 25.75	\$ 42.50	\$ -	\$ -	\$ 68.25
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	12850	Feb-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	12850	Feb-14	\$ 618.00	\$ 85.00	\$ -	\$ -	\$ 703.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	12850	Feb-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect Flitstep Kit	AAI Flitstep kit IAW AA-01162 Rev E	Inspection	300	12850	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect Rotor Brake Assy	IAW 600 Hr Inspection Chptr 5-20	Inspection	600	12850	Feb-14	\$ 25.75	\$ 170.00	\$ -	\$ -	\$ 195.75
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	12850	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Progressive inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	300	12850	Feb-14	\$ 206.00	\$ 3,400.00	\$ -	\$ -	\$ 3,606.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	12850	Feb-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Tailboom Inspection	Insp Tailboom 407-030-801-205 Per Fig 4-5	Inspection	300	12850	Feb-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	12850	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12853.8	Feb-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12853.8	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	12	12877	Feb-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change Eng Oil with Royco 560	IAW Rolls Royce Series MM Chptr 72 Tbl 604	Inspection	12	12877	Feb-14	\$ 309.00	\$ 85.00	\$ -	\$ -	\$ 394.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	12903.8	Mar-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	12903.8	Mar-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12903.8	Mar-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12903.8	Mar-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	12903.8	Mar-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	12903.8	Mar-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50

21716	Gimbal Arms	Retire	84	12928.8	Mar-14	\$ 20,600.00	\$ 340.00	\$ 100.00	\$ -	\$ 21,040.00
Hydraulic By-pass Spool Inspection	Inspect hydraulic servo by-pass spool IAW BHT-407-MM	Inspection	24	12928.8	Apr-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Inspect Fuel System	IAW Chptr 5-23	Inspection	24	12928.8	Apr-14	\$ -	\$ 510.00	\$ -	\$ -	\$ 510.00
M/R Flight Control Bolts	IAW Chptr 5-23	Inspection	24	12928.8	Apr-14	\$ -	\$ 510.00	\$ -	\$ -	\$ 510.00
Pitot Static Sys & Altimeter	IAW FAR 91.411(a)	Inspection	24	12928.8	Apr-14	\$ -	\$ 510.00	\$ -	\$ -	\$ 510.00
Spring Link Assy	IAW Chptr 5-23	Inspection	24	12928.8	Apr-14	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
Transponder Biennial Check	IAW FAR 91.413(a)	Inspection	24	12928.8	Apr-14	\$ -	\$ 340.00	\$ -	\$ -	\$ 340.00
206-340-300-107	Input Driveshaft	Retire	5000	12953.4	Apr-14	\$ 41,759.29	\$ 340.00	\$ 100.00	\$ -	\$ 42,199.29
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	12953.8	Apr-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	12953.8	Apr-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	12953.8	Apr-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
300HR Search Light Insp	IAW SIO899-01A	Inspection	300	12999.8	May-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	12999.8	May-14	\$ 103.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,248.00
23078031	Hmu	Overhaul	2500	13000	May-14	\$ 37,080.00	\$ 510.00	\$ 50.00	\$ -	\$ 37,640.00
407-040-006-107FMS	Transmission	Overhaul	4500	13000	May-14	\$ 2,575.00	\$ 10,625.00	\$ 50.00	\$ -	\$ 13,250.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13003.8	May-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13003.8	May-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13003.8	May-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13003.8	May-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13003.8	May-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13003.8	May-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13053.8	Jun-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13053.8	Jun-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
23073353	Bleed Valve	Overhaul	1500	13063.5	Jun-14	\$ 3,605.00	\$ 340.00	\$ 25.00	\$ -	\$ 3,970.00
Replace ELT Batetry	IAW FAR 91.207(d)	Inspection	53	13084.2	Jul-14	\$ 257.50	\$ 85.00	\$ 25.00	\$ -	\$ 367.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13103.8	Jul-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13103.8	Jul-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13103.8	Jul-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13103.8	Jul-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13103.8	Jul-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13103.8	Jul-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13103.8	Jul-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13149.8	Aug-14	\$ 103.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,248.00
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	13150	Aug-14	\$ 77.25	\$ 1,360.00	\$ -	\$ -	\$ 1,437.25
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	13150	Aug-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	13150	Aug-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	13150	Aug-14	\$ 103.00	\$ 85.00	\$ -	\$ -	\$ 188.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	13150	Aug-14	\$ 25.75	\$ 42.50	\$ -	\$ -	\$ 68.25
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	13150	Aug-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	13150	Aug-14	\$ 618.00	\$ 85.00	\$ -	\$ -	\$ 703.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	13150	Aug-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect Flitestep Kit	AAI Flitestep kit IAW AA-01162 Rev E	Inspection	300	13150	Aug-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	13150	Aug-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Progressive inspection Events 1-6	IAW Bel Helicopters MM Chptr 5-13 & 14	Inspection	300	13150	Aug-14	\$ 206.00	\$ 3,400.00	\$ -	\$ -	\$ 3,606.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	13150	Aug-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Tailboom Inspection	Insp Tailboom 407-030-801-205 Per Fig 4-5	Inspection	300	13150	Aug-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	13150	Aug-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13153.8	Aug-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13153.8	Aug-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13203.8	Sep-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13203.8	Sep-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13203.8	Sep-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13203.8	Sep-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13203.8	Sep-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13203.8	Sep-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13253.8	Oct-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13253.8	Oct-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50

Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13253.8	Oct-14	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
300HR Search Light Insp	IAW SI0899-01A	Inspection	300	13299.8	Nov-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13299.8	Nov-14	\$ 103.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,248.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13303.8	Nov-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13303.8	Nov-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13303.8	Nov-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13303.8	Nov-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13303.8	Nov-14	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13303.8	Nov-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13353.8	Dec-14	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13353.8	Dec-14	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
600 hr/12 month m/r blade insp.	IAW Chptr 5-21	Inspection	600	13363.5	Dec-14	\$ -	\$ 170.00	\$ -	\$ -	\$ 170.00
Inspection Of M/R Mast	Inspect M/R mast IAW ASB 407-11-94	Inspection	600	13363.5	Dec-14	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13403.8	Jan-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13403.8	Jan-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13403.8	Jan-15	\$ 51.50	\$ 85.00	\$ -	\$ -	\$ 136.50
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13403.8	Jan-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Change Eng Oil with Royco 560	IAW Rolls Royce Series MM Chptr 72 Tbl 604	Inspection	600	13403.8	Jan-15	\$ 309.00	\$ 85.00	\$ -	\$ -	\$ 394.00
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13403.8	Jan-15	\$ 77.25	\$ 85.00	\$ -	\$ -	\$ 162.25
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13403.8	Jan-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13403.8	Jan-15	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13449.8	Feb-15	\$ 106.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,251.00
300 HR Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 604	Inspection	300	13450	Feb-15	\$ 79.50	\$ 1,360.00	\$ -	\$ -	\$ 1,439.50
300 Hr/ Annual Pedal Extension Insp	IAW Paravion Technology ICA PR-407PX-120M	Inspection	300	13450	Feb-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
300 Hr/Annual High Skid Gear	AAI High Skid Gear Insp (I.A.W AA-00061)	Inspection	300	13450	Feb-15	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
407-340-302-101	Rotor Brake Caliper	Overhaul	1800	13450	Feb-15	\$ 3,710.00	\$ 850.00	\$ -	\$ -	\$ 4,560.00
407-340-302-101	Rotor Brake Caliper	Overhaul	1800	13450	Feb-15	\$ 3,710.00	\$ 850.00	\$ -	\$ -	\$ 4,560.00
407-340-318-101	Rotor Brake Disk	Inspection	600	13450	Feb-15	\$ -	\$ 340.00	\$ -	\$ -	\$ 340.00
Change M/R Xmsn Oil with Royco 555 & M/R Filter	IAW Chptr 12 Tbl 12-3	Inspection	300	13450	Feb-15	\$ 106.00	\$ 85.00	\$ -	\$ -	\$ 191.00
Change T/R/G/B Oil with Royco 555	IAW Chptr 12 Tbl 12-3	Inspection	300	13450	Feb-15	\$ 26.50	\$ 42.50	\$ -	\$ -	\$ 69.00
Chg A/F Fuel Filter	IAW Chptr 12 Tbl 12-1	Inspection	300	13450	Feb-15	\$ 79.50	\$ 85.00	\$ -	\$ -	\$ 164.50
Clean or Change hydraulic Filters & Change Fluid	IAW Chptr 12 Tbl 12-3	Inspection	300	13450	Feb-15	\$ 636.00	\$ 85.00	\$ -	\$ -	\$ 721.00
Inspect and Lube T/R/D/S Hangar Bearings	IAW ASB 407-04-63 Rev. B & AD 2004-10-07	Inspection	300	13450	Feb-15	\$ 79.50	\$ 85.00	\$ -	\$ -	\$ 164.50
Inspect Flitstep Kit	AAI Flitstep kit IAW AA-01162 Rev E	Inspection	300	13450	Feb-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Inspect Rotor Brake Assy	IAW 600 Hr Inspection Chptr 5-20	Inspection	600	13450	Feb-15	\$ 26.50	\$ 170.00	\$ -	\$ -	\$ 196.50
Inspect T/R Blades	ASB 407-10-92 Tail Rotor Blade Rev. A	Inspection	300	13450	Feb-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Progressive inspection Events 1-6	IAW Bel IHelicopters MM Chptr 5-13 & 14	Inspection	300	13450	Feb-15	\$ 212.00	\$ 3,400.00	\$ -	\$ -	\$ 3,612.00
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	300	13450	Feb-15	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
Tailboom Inspection	Insp Tailboom 407-030-801-205 Per Fig 4-5	Inspection	300	13450	Feb-15	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
Torque Check T/R Mast nut	IAW Special Inspection Chptr 5-19 Tbl 5-2	Inspection	300	13450	Feb-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13453.8	Feb-15	\$ 53.00	\$ 85.00	\$ -	\$ -	\$ 138.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13453.8	Feb-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13503.8	Mar-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13503.8	Mar-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13503.8	Mar-15	\$ 53.00	\$ 85.00	\$ -	\$ -	\$ 138.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13503.8	Mar-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Insp/Lube T/R D/S Splines	IAW Chptr 12 Tbl 12-1	Inspection	100	13503.8	Mar-15	\$ 79.50	\$ 85.00	\$ -	\$ -	\$ 164.50
Inspect M/R Yoke	Per Figure 4-2	Inspection	100	13503.8	Mar-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13553.8	Apr-15	\$ 53.00	\$ 85.00	\$ -	\$ -	\$ 138.00
C/W ASB 407-11-95 Upper Left Longeron Insp	Inspect Upper Left Longeron	Inspection	50	13553.8	Apr-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
Service Battery	Deep Cycle 300 Hr/ Top Charge 150 Hr	Inspection	150	13553.8	Apr-15	\$ -	\$ 255.00	\$ -	\$ -	\$ 255.00
406-310-405-101	Bearing (Or)	Retire	5000	13595.4	Apr-15	\$ 2,839.74	\$ 170.00	\$ -	\$ -	\$ 3,009.74
300HR Search Light Insp	IAW SI0899-01A	Inspection	300	13599.8	Apr-15	\$ -	\$ 85.00	\$ -	\$ -	\$ 85.00
C/W 150 Hr Engine Inspection	IAW Rolls Royce Series Manual Chptr 72 Tbl 603	Inspection	150	13599.8	Apr-15	\$ 106.00	\$ 1,020.00	\$ 125.00	\$ -	\$ 1,251.00
100 Hour/Annual Insp Monitor Mount	Monitor Mount Insp I.A.W PR-407MM-120M	Inspection	100	13603.8	May-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
100Hr/6Mo Skid Tube Insp	AAI Skid Tube Insp I.A.W AA-01141	Inspection	100	13603.8	May-15	\$ -	\$ 42.50	\$ -	\$ -	\$ 42.50
50 HR	Grease Requirements IAW Chptr 12 Tbl 12-2	Inspection	50	13603.8	May-15	\$ 53.00	\$ 85.00	\$ -	\$ -	\$ 138.00

